Case: 1:10 ov 05684 Decument #: 208 10 Filed: 06/22/22 Dage 1 of 1 DageID #:2602

BRAL RESTORATION, LLC

BUILDING RESTORATION SPECIALISTS • CONSULTATION BUDGET PREPARATION • TECHNICAL SERVICES

May 3, 2018

Mr. John Gorr 2726 West Cortez Condominium Association Unit 3 Chicago, IL 60622

Phone: 773-742-0596 Email: jgorr1@msn.com

Water Leak Investigation Results:

We arrived on site at approximately 8am on May 2, 2018. A 3-man crew provided protection to the surrounding areas inside the 3rd floor. We removed the drapery and drywall as needed to inspect the back side at interior of wall during the water leak investigation. We accessed the west wall with built up pipe scaffolding. We conducted the water leak test with standard water pressure from the building.

We completed similar protection and opening above the North door of 3rd floor.

At both locations we were able to produce water leakage within 10 minutes of spraying water. We complete the test 2 x's with same results.

The removal of drywall allowed BRAL to confirm there is not a cavity wall system to be repaired and or reviewed. The existing flashing was through wall that allowed water to penetrate right into the back of block.

It was decided to not continue with reviewing any further window or door openings besides these two. It was explained that installing a cavity wall system over just the masonry openings and allowing a proper through wall flashing system to be installed would not prevent water from penetrating at locations in between the openings.

A previous proposal including as needed repointing and application of 2 coats of Modac was modified to include the application of 1 coat of Chem-Trete as an alternative.

The photo documentation, revised proposal, time & material sheet and credit invoice is herein included.

Please call with any questions. Thank you.

Regards,

Al Christoffer Bral Restoration, LLC 847-456-5172

aL Christoffer

EXH 21 PART II